

FIG.1A




FIG.1B

0986604-11301

09986804-11301




FIG.2




FIG. 3



**FIG.4**

FIG.5

FIG.5A
FIG.5B

FIG.5A








FIG.5B

090904 4089360



LAST PRINTED IMAGE

FIG.6A



DOT PATTERN FORMED DURING
PRELIMINARY EJECTING OPERATION

FIG.6B




FIG.7


098834 11301

FIG.8

FIG.8A

FIG.8B

FIG.8A




[illegible]

FIG. 8B